# Energy performance certificate (EPC) recommendation report

259 Poulton Road POULTON CH44 4BT Report number **5425-4189-6905-1307-2036** 

Valid until

16 January 2032

**Potential** 

Medium

#### **Energy rating and EPC**

This property's current energy rating is F.

For more information on the property's energy performance, <u>see the EPC for this property (/energy-certificate/3459-9021-9793-0521-2401)</u>.

#### Recommendations

Recommendation

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

## Changes that pay for themselves within 3 years

Some solid walls are poorly insulated - introduce or improve internal wall insulation.

	impact
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	High
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.	Medium
Changes that pay for themselves within 3 to 7 years	
Recommendation	Potential impact
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Some loft spaces are poorly insulated - install/improve insulation.	Medium

Recommendation	Potential impact
Consider replacing heating boiler plant with a condensing type.	Medium
Changes that pay for themselves in more than 7 years	
Recommendation	Potential impact
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Consider installing building mounted wind turbine(s).	Low
Consider installing solar water heating.	Low
Roof is poorly insulated. Install or improve insulation of roof.	Medium
Property and report details	
Report issued on	
17 January 2022	
Total useful floor area	
144 square metres	
Building environment	
Heating and Natural Ventilation	

## Calculation tool

DesignBuilder Software Ltd, DesignBuilder SBEM, v6.1.8, SBEM, v5.6.b.0

#### Assessor's details

#### Assessor's name

Oliver Craven

## **Telephone**

0333 1211201

#### **Email**

craven@cpaa.co

## Employer's name

## The EPC Man

### **Employer's address**

20 Melford Grove Liverpool L6 4DN

#### **Assessor ID**

EES/012159

#### Assessor's declaration

The assessor is not related to the owner of the property.

#### **Accreditation scheme**

Elmhurst Energy Systems Ltd

#### Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <a href="mailto:dluhc.digital-services@levellingup.gov.uk">dluhc.digital-services@levellingup.gov.uk</a> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related reports for this property.