



# Electrical Installation Condition Report

for Domestic and Similar Premises up to 100 A  
 Requirements for Electrical Installations  
 BS 7671:2018 (IET Wiring Regulations 18th Edition)

NIC 16 Slatey Rd  
 Flats 01-09-21  
 2 1 0 8 8 0 0 0 0 1 3 0 7  
 EICR

Page 2 of 6

## A Details of the Installation

Client	Macmaster Properties	Installation	Flat 1 16 Slatey Road
Address	Macmaster Properties 80 Balls Road Prenton Wirral Merseyside	Address	Flat 1 16 Slatey Road Wirral Merseyside
Postcode	CH43 1US	Postcode	CH43 4UE

## B Reason for producing this report *This form is to be used only for reporting on the condition of an existing installation.*

Periodic inspection and test

Date(s) on which the inspection and testing were carried out 01/09/2021 to 01/09/2021

## C Details of installation which is the subject of this report

Description of premises	Domestic <input checked="" type="checkbox"/>	Commercial <input type="checkbox"/>	Industrial <input type="checkbox"/>	Other (please specify)
Estimated age of the wiring system	30	years		
Evidence of alterations or addition	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Not apparent <input type="checkbox"/>	If 'Yes', estimated years
Records of installation available	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Records held by	
Date of last inspection	Not Known			Electrical Installation Certificate No. or previous Inspection Report No.

## D Extent of electrical installation covered by this report:

80% Tests Where Possible  
40% Visual

### Agreed Limitations and Operational Limitations (Regulations 653.2)

No Floorboards Lifted  
Loft Not Inspected

Operational limitations including the reasons see page no 1

Agreed with: Client

The inspection and testing detailed within this report and accompanying schedule has been carried out in accordance with BS 7671: 2018 amended to 2018

It should be noted that cables concealed within trunkings and conduits, under floors, in roof spaces and generally within the fabric of the building or underground have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.

## E Summary of the condition of the installation

General conditions of the installation (in terms of safety)

Ok, Satisfactory

Overall assessment of the installation in terms of its suitability for continued use

SATISFACTORY  \*UNSATISFACTORY

\*An UNSATISFACTORY assessment indicates that dangerous (code C1), or potentially dangerous (code C2). Further investigation (code F1) conditions have been identified

## F Recommendations

Where the overall assessment of the suitability of the installation for continued use above is stated as UNSATISFACTORY we recommend that any observations classified as 'Danger present' (code C1) or 'Potential dangerous' (code C2) are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as 'Further investigation required' (code F1). Observations classified as 'Improvement recommended' (code C3) should be given due consideration. Subject to the necessary remedial action being taken, we recommend that the installation is further inspected and tested by 01/08/2026 (date)

## G Declaration

We being the person(s) responsible for the inspection and the testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described above, having exercised reasonable skill and care when carrying out the inspection and testing hereby declare that the information in this report, including the observations and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent and limitations in section D of this report.

Company A.R. Electrical

Inspected and tested by

Authorised for issue by

Membership No. 21068

Name: Aaron Rogan

Aaron Rogan

Address 50 Edgehill Road, WIRRAL, Merseyside

Signature: Aaron Rogan

Aaron Rogan

Postcode CH46 6AW

Position:

Date: 01/09/2021

01/09/2021

## H Schedule(s)

1 schedule(s) of inspection and 1 schedule(s) of test results are attached.

The attached schedule(s) are part of this document and this report is valid only when they are attached to it.



# Electrical Installation Condition Report

for Domestic and Similar Premises up to 100 A  
 Requirements for Electrical Installations  
 BS 7671:2018 (IET Wiring Regulations 18th Edition)

NA 2 1 0 8 8 0 0 0 0 1 3 0 2  
 EICR

Page 2 of 6

F2 16 Slatey  
 1-9-21

## A Details of the Installation

Client	Macmaster Properties	Installation	Flat 2 16 Slatey Road
Address	Macmaster Properties 80 Balls Road Prenton Wirral Merseyside	Address	Flat 2 16 Slatey Road Wirral Merseyside
Postcode	CH43 1US	Postcode	CH43 4UE

## B Reason for producing this report *This form is to be used only for reporting on the condition of an existing installation.*

Periodic inspection and test

Date(s) on which the inspection and testing were carried out 01/09/2021 to 01/09/2021

## C Details of installation which is the subject of this report

Description of premises	Domestic <input checked="" type="checkbox"/>	Commercial <input type="checkbox"/>	Industrial <input type="checkbox"/>	Other (please specify)
Estimated age of the wiring system	30	years		
Evidence of alterations or addition	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Not apparent <input type="checkbox"/>	if 'Yes', estimated years
Records of installation available	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>	Records held by	
Date of last inspection	Not Known			Electrical Installation Certificate No. or previous Inspection Report No.

## D Extent of electrical installation covered by this report:

80% Tests Where Possible  
 40% Visual

### Agreed Limitations and Operational Limitations (Regulations 653.2)

No Floorboards Lifted  
 Loft Not Inspected

Operational limitations including the reasons see page no 1

Agreed with: Client

The inspection and testing detailed within this report and accompanying schedule has been carried out in accordance with BS 7671: 2018 amended to 2018

It should be noted that cables concealed within trunkings and conduits, under floors, in roof spaces and generally within the fabric of the building or underground have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.

## E Summary of the condition of the installation

General conditions of the installation (in terms of safety)

Ok, Satisfactory

Overall assessment of the installation in terms of its suitability for continued use

SATISFACTORY

\*UNSATISFACTORY

\*An UNSATISFACTORY assessment indicates that dangerous (code C1), or potentially dangerous (code C2), Further investigation (code F1) conditions have been identified

## F Recommendations

Where the overall assessment of the suitability of the installation for continued use above is stated as UNSATISFACTORY /we recommend that any observations classified as 'Danger present' (code C1) or 'Potential dangerous' (code C2) are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as 'Further Investigation required' (code F1). Observations classified as 'Improvement recommended' (code C3) should be given due consideration. Subject to the necessary remedial action being taken, /we recommend that the installation is further inspected and tested by 01/08/2026 (date)

## G Declaration

We being the person(s) responsible for the inspection and the testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described above, having exercised reasonable skill and care when carrying out the inspection and testing hereby declare that the information in this report, including the observations and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent and limitations in section D of this report.

Company	A.R. Electrical	Inspected and tested by	Authorised for issue by
Membership No.	21088	Name: Aaron Rogan	Aaron Rogan
Address	50 Edgehill Road, WIRRAL, Merseyside	Signature: Aaron Rogan	Aaron Rogan
Postcode	CH46 6AW	Position: Date: 01/09/2021	01/09/2021

## H Schedule(s)

1 schedule(s) of inspection and 1 schedule(s) of test results are attached

The attached schedule(s) are part of this document and this report is valid only when they are attached to it.



## Electrical Installation Condition Report

for Domestic and Similar Premises up to 100 A  
 Requirements for Electrical Installations  
 BS 7671:2018 (IET Wiring Regulations 18th Edition)

NAV 2 1 0 8 8 0 0 0 0 0 1 3 0 4

EICR

Page 2 of 6

### A Details of the Installation

Client	Macmaster Properties	Installation	Flat 3 16 Slatey Road
Address	Macmaster Properties 80 Balls Road Prenton Wirral Merseyside	Address	Flat 3 16 Slatey Road Wirral Merseyside
Postcode	CH43 1US	Postcode	CH43 4UE

### B Reason for producing this report *This form is to be used only for reporting on the condition of an existing installation.*

Periodic inspection and test

Date(s) on which the inspection and testing were carried out 01/09/2021 to 01/09/2021

### C Details of installation which is the subject of this report

Description of premises Domestic  Commercial  Industrial  Other (please specify)

Estimated age of the wiring system 30 years

Evidence of alterations or addition Yes  No  Not apparent  if 'Yes', estimated years

Records of installation available Yes  No  Records held by

Date of last inspection Not Known Electrical Installation Certificate No. or previous Inspection Report No.

### D Extent of electrical installation covered by this report: Agreed Limitations and Operational Limitations (Regulations 653.2)

80% Tests Where Possible

40% Visual

No Floorboards Lifted

Loft Not Inspected

Operational limitations including the reasons see page no 1

Agreed with: Client

The inspection and testing detailed within this report and accompanying schedule has been carried out in accordance with BS 7671: 2018 amended to 2018

It should be noted that cables concealed within trunkings and conduits, under floors, in roof spaces and generally within the fabric of the building or underground have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.

### E Summary of the condition of the installation

General conditions of the installation (in terms of safety)

Ok, Satisfactory

Overall assessment of the installation in terms of its suitability for continued use

SATISFACTORY

\*UNSATISFACTORY

\*An UNSATISFACTORY assessment indicates that dangerous (code C1), or potentially dangerous (code C2), Further investigation (code FI) conditions have been identified

### F Recommendations

Where the overall assessment of the suitability of the installation for continued use above is stated as UNSATISFACTORY we recommend that any observations classified as 'Danger present' (code C1) or 'Potential dangerous' (code C2) are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as 'Further Investigation required' (code FI). Observations classified as 'Improvement recommended' (code C3) should be given due consideration. Subject to the necessary remedial action being taken, we recommend that the installation is further inspected and tested by 01/08/2026 (date)

### G Declaration

I/we being the person(s) responsible for the inspection and the testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described above, having exercised reasonable skill and care when carrying out the inspection and testing hereby declare that the information in this report, including the observations and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent and limitations in section D of this report.

Company A.R. Electrical

Inspected and tested by

Authorised for issue by

Membership No. 21088

Name: Aaron Rogan

Aaron Rogan

Address 50 Edgehill Road, WIRRAL, Merseyside

Signature: Aaron Rogan

Aaron Rogan

Postcode CH46 6AW

Position:

01/09/2021

Date: 01/09/2021

01/09/2021

### H Schedule(s)

1 schedule(s) of inspection and 1 schedule(s) of test results are attached.

The attached schedule(s) are part of this document and this report is valid only when they are attached to it.



## Electrical Installation Condition Report

for Domestic and Similar Premises up to 100 A  
 Requirements for Electrical Installations  
 BS 7671:2018 (IET Wiring Regulations 18th Edition)

NA 2 1 0 8 8 0 0 0 0 1 3 0 : 5  
 EICR

Page 2 of 6

### A Details of the Installation

Client	Macmaster Properties	Installation	Flat 4 16 Slatey Road
Address	Macmaster Properties 80 Balls Road Prenton Wirral Merseyside	Address	Flat 4 16 Slatey Road Wirral Merseyside
Postcode	CH431US	Postcode	CH43 4UE

### B Reason for producing this report. This form is to be used only for reporting on the condition of an existing installation.

Periodic inspection and test

Date(s) on which the inspection and testing were carried out 01/09/2021 to 01/09/2021

### C Details of installation which is the subject of this report

Description of premises Domestic  Commercial  Industrial  Other (please specify)

Estimated age of the wiring system 30 years

Evidence of alterations or addition Yes  No  Not apparent  if 'Yes', estimated yearsRecords of installation available Yes  No  Records held by

Date of last inspection Not Known Electrical Installation Certificate No. or previous Inspection Report No.

### D Extent of electrical installation covered by this report:

80% Tests Where Possible  
40% Visual

#### Agreed Limitations and Operational Limitations (Regulations 653.2)

No Floorboards Lifted  
Loft Not Inspected

Operational limitations including the reasons see page no 1

Agreed with: Client

The inspection and testing detailed within this report and accompanying schedule has been carried out in accordance with BS 7671: 2018 amended to 2018

It should be noted that cables concealed within trunkings and conduits, under floors, in roof spaces and generally within the fabric of the building or underground have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.

### E Summary of the condition of the installation

General conditions of the installation (in terms of safety)

Ok, Satisfactory

 SATISFACTORY \*UNSATISFACTORY

\*An UNSATISFACTORY assessment indicates that dangerous (code C1), or potentially dangerous (code C2), Further investigation (code F1) conditions have been identified

### F Recommendations

Where the overall assessment of the suitability of the installation for continued use above is stated as UNSATISFACTORY /we recommend that any observations classified as 'Danger present' (code C1) or 'Potential dangerous' (code C2) are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as 'Further Investigation required' (code F1). Observations classified as 'Improvement recommended' (code C3) should be given due consideration. Subject to the necessary remedial action being taken, /we recommend that the installation is further inspected and tested by 01/08/2026 (date)

### G Declaration

I/we being the person(s) responsible for the inspection and the testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described above, having exercised reasonable skill and care when carrying out the inspection and testing hereby declare that the information in this report, including the observations and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent and limitations in section D of this report.

Company	A.R. Electrical
Membership No.	21088
Address	50 Edgehill Road, WIRRAL, Merseyside
Postcode	CH46 6AW

Name:	Aaron Rogan	Inspected and tested by
Signature:	<i>Aaron Rogan</i>	Authorised for issue by
Position:		<i>Aaron Rogan</i>
Date:	01/09/2021	01/09/2021

### H Schedule(s)

1 schedule(s) of inspection and 1 schedule(s) of test results are attached.

The attached schedule(s) are part of this document and this report is valid only when they are attached to it.



## Electrical Installation Condition Report

for Domestic and Similar Premises up to 100 A

Requirements for Electrical Installations

BS 7671:2018 (IET Wiring Regulations 18th Edition)

NAV 2 1 0 8 8 0 0 0 0 0 1 3 0 6

EICR

Page 2 of 6

### A Details of the Installation

Client	Macmaster Properties	Installation	Flat 5 16 Slatey Road
Address	Macmaster Properties 80 Balls Road Prenton Wirral Merseyside	Address	Flat 5 16 Slatey Road Wirral Merseyside
Postcode	CH43 1US	Postcode	CH43 4UE

### B Reason for producing this report *This form is to be used only for reporting on the condition of an existing installation.*

Periodic inspection and test

Date(s) on which the inspection and testing were carried out 01/09/2021 to 01/09/2021

### C Details of installation which is the subject of this report

Description of premises Domestic  Commercial  Industrial  Other (please specify)

Estimated age of the wiring system 30 years

Evidence of alterations or addition Yes  No  Not apparent  if 'Yes', estimated years

Records of installation available Yes  No  Records held by

Date of last inspection Not Known Electrical Installation Certificate No. or previous Inspection Report No.

### D Extent of electrical installation covered by this report:

80% Tests Where Possible  
40% Visual

#### Agreed Limitations and Operational Limitations (Regulations 653.2)

No Floorboards Lifted  
Loft Not Inspected

Operational limitations including the reasons see page no 1

Agreed with: Client

The inspection and testing detailed within this report and accompanying schedule has been carried out in accordance with BS 7671: 2018 amended to 2018

It should be noted that cables concealed within trunkings and conduits, under floors, in roof spaces and generally within the fabric of the building or underground have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.

### E Summary of the condition of the installation

General conditions of the installation (in terms of safety)

Ok, Satisfactory

Overall assessment of the installation in terms of its suitability for continued use

SATISFACTORY  UNSATISFACTORY

\*An UNSATISFACTORY assessment indicates that dangerous (code C1), or potentially dangerous (code C2), Further investigation (code F1) conditions have been identified

### F Recommendations

Where the overall assessment of the suitability of the installation for continued use above is stated as UNSATISFACTORY /we recommend that any observations classified as 'Danger present' (code C1) or 'Potential dangerous' (code C2) are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as 'Further Investigation required' (code F1). Observations classified as 'Improvement recommended' (code C3) should be given due consideration. Subject to the necessary remedial action being taken, /we recommend that the installation is further inspected and tested by 01/08/2026 (date)

### G Declaration

/we being the person(s) responsible for the inspection and the testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described above, having exercised reasonable skill and care when carrying out the inspection and testing hereby declare that the information in this report, including the observations and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent and limitations in section D of this report.

Company A.R. Electrical

Inspected and tested by

Authorised for issue by

Membership No. 21088

Name: Aaron Rogan

Aaron Rogan

Address 50 Edgehill Road, WIRRAL, Merseyside

Signature: Aaron Rogan

Aaron Rogan

Postcode CH46 6AW

Position:

Date: 01/09/2021

01/09/2021

### H Schedule(s)

1 schedule(s) of inspection and 1 schedule(s) of test results are attached.

The attached schedule(s) are part of this document and this report is valid only when they are attached to it.

104, 16 f1 14 slatey Rd

## Building Regulations Compliance Certificate



NAPIT has notified your Local Authority Building Control of the installation work detailed on this certificate. The installer (named below) confirms that the work completed at the address shown below complies with Regulations 4 and 7 of the Building Regulations.

### Certificate Delivery Address

**The Occupier**  
MacMaster Properties Exchange House  
80 Balls Road  
PRENTON  
Merseyside  
CH43 1US      327 / 159

*Address of where the installation was carried out:*

### Flat 1

14 Slatey Road  
PRENTON  
Merseyside  
CH43 4UF

### Schedule of Work:

Install a replacement consumer unit / Flat Dwelling

**Certificate Number:** 1514647  
**Work Completion Date:** 10/04/2016  
**NAPIT Registration No:** 21088  
**Installation Company:** A.R. Electrical

This certificate is issued by NAPIT Registration Ltd on behalf of the named installation company in accordance with Regulation 20 of the Building Regulations. Regulation 20(5) states that a certificate given in accordance with this regulation shall be evidence (but not conclusive evidence) that the requirements specified in the certificate have been complied with.

10 . 4 . 16 F3 14 Shattoe Rd

## Building Regulations Compliance Certificate



NAPIT has notified your Local Authority Building Control of the installation work detailed on this certificate. The installer (named below) confirms that the work completed at the address shown below complies with Regulations 4 and 7 of the Building Regulations.

### Certificate Delivery Address

**The Occupier**  
**MacMaster Properties Exchange House**  
**80 Balls Road**  
**PRENTON**  
**Merseyside**  
**CH43 1US**

*Address of where the installation was carried out:*

**Flat 3**  
**14 Slates Road**  
**PRENTON**  
**Merseyside**  
**CH43 4UF**

### Schedule of Work:

Install a replacement consumer unit / Flat Dwelling

**Certificate Number:** 1514651  
**Work Completion Date:** 10/04/2016  
**NAPIT Registration No:** 21088  
**Installation Company:** A.R. Electrical

This certificate is issued by NAPIT Registration Ltd on behalf of the named installation company in accordance with Regulation 20 of the Building Regulations. Regulation 20(5) states that a certificate given in accordance with this regulation shall be evidence (but not conclusive evidence) that the requirements specified in the certificate have been complied with.

10, 4, 16 F2 14 Slatley Rd

## Building Regulations Compliance Certificate



NAPIT has notified your Local Authority Building Control of the installation work detailed on this certificate. The Installer (named below) confirms that the work completed at the address shown below complies with Regulations 4 and 7 of the Building Regulations.

### Certificate Delivery Address

#### The Occupier

#### MacMaster Properties Exchange House

80 Balls Road

PRENTON

Merseyside

CH43 1US

327 / 160

### Address of where the installation was carried out:

**Flat 2  
14 Slatley Road  
PRENTON  
Merseyside  
CH43 4UF**

### Schedule of Work:

Install a replacement consumer unit / Flat Dwelling

**Certificate Number: 1514650**

**Work Completion Date: 10/04/2016**

**NAPIT Registration No: 21088**

**Installation Company: A.R. Electrical**

This certificate is issued by NAPIT Registration Ltd on behalf of the named installation company in accordance with Regulation 20 of the Building Regulations. Regulation 20(5) states that a certificate given in accordance with this regulation shall be evidence (but not conclusive evidence) that the requirements specified in the certificate have been complied with.

14 SLATEY RD.  
30/03/16.

Original (To the person ordering the work)

Contractor's Reference Number

CRN/

# DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT (FOR A SINGLE DWELLING)

Issued in accordance with British Standard 7671 – Requirements for Electrical Installations.

## A. DETAILS OF THE CLIENT

Client:

MANNION PRENTER

Address:  
30 BATES ROAD, OXFORD, OX2 0AE,  
MORSEYS 105.

Postcode:

## B. PURPOSE OF THE REPORT

Purpose  
OF INSPECTION WAS CONCERN THIN/10  
Years.

Dates) on which inspection  
and testing were carried out:  
30/03/16

Extent of the electrical installation covered by this report:  
*401. outside*

Agreed limitations including the reasons (see page No.)  
*at none.*

Agreed with *C.C. / C.J.T.*

## D. EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE INSPECTION AND TESTING

Extent of the electrical installation covered by this report:

*401. outside*

Agreed limitations including the reasons, if any, on the inspection and testing:  
*100% TEST CHARTER PASS*

None.

Operational limitations including the reasons (see page No.)  
*at none.*

Operational limitations including the reasons (see page No.)  
*at none.*

The inspection and testing have been carried out in accordance with BS 7671, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the client and inspector prior to the inspection.

## C. DETAILS OF THE INSTALLATION

Occupier: *COLIN MANNION D.B.*

Address: *14 SLATEY RD, OXFORD, OX2 0AE,  
MORSEYS 105.*

Estimated age of the  
electrical installation:  
*30 years*

If yes,  
estimated  
age

✓ 10 years

Evidence of alterations  
or additions

✓ Yes  
Specify page No(s):

An unsatisfactory assessment indicates that dangerous  
(CODE C1) and/or potentially dangerous (CODE C2) conditions  
have been identified, or that further investigation without  
delay (f) is required

SATISFACTORY / UNSATISFACTORY\*

Overall assessment  
of the installation:

✓ Delete as appropriate

## E. SUMMARY OF THE CONDITION OF THE INSTALLATION

General condition of the installation (in terms of electrical safety):  
*OK*

Records held by: *C.C. / C.J.T.*

Please see the 'Notes for Recipients'  
on the reverse of this page.

DPM4/2108800824

## Contractor's Reference Number

CRN/

## DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT (FOR A SINGLE DWELLING)

Issued in accordance with British Standard 7671 - Requirements for Electrical Installations.

## DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT (FOR A SINGLE DWELLING)

## A. DETAILS OF THE CLIENT

Client: Achilles Resources Ltd.Address: 20 Bals Road, Oxfordshire, MertonPostcode: OX14 9JG

## B. PURPOSE OF THE REPORT

Purpose for which this report is required:  
Check of consumer unit & removal works  
Carried out after initial test.Date(s) on which inspection and testing were carried out: 31/03/16.

## C. DETAILS OF THE INSTALLATION

Occupier: John /  
Address: 14 Scar Lane, Oxford, MertonPostcode: OX14 9JG  
Estimated age of the electrical installation: 30 years  
If yes, estimated age: 10 yearsEvidence of alterations or additions: ✓  
Records held by: JohnElectrical Installation Certificate No or previous Periodic Inspection or Condition Report No: ✓  
Records of installation available: ✓

## D. EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE INSPECTION AND TESTING

Extent of the electrical installation covered by this report:

40v. visual  
100v. tests.Agreed limitations including the reasons, if any, on the inspection and testing:  
No fair earth tested, can not inspect.Agreed with: CERT.  
Operational limitations including the reasons (see page No. 1)  
None.

The inspection and testing have been carried out in accordance with BS 7671, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the client and inspector prior to the inspection.

## E. SUMMARY OF THE CONDITION OF THE INSTALLATION

General condition of the installation (in terms of electrical safety): OK.Summary of the condition of the installation continued on additional pages? No Yes Specify page No(s).  
Overall assessment of the installation: SATISFACTORY / UNSATISFACTORY\* An 'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that further investigation without delay (F1) is required  
Delete as appropriate

DPM4/208800825,

Contractor's Reference Number

CRN/

**DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT (FOR A SINGLE DWELLING)**

Issued in accordance with British Standard 7671 - Requirements for Electrical Installations.

**A. DETAILS OF THE CLIENT**Client: **WILMINGTON BUILDINGS LTD.**Address: **80 BAUS ROAD, EXTON, WILMINGTON,  
NERSEYSIDE.**

Postcode:

**B. PURPOSE OF THE REPORT**Purpose for which this report is required:  
**CHANGE OF CABLES ON ST & ROOFLINE  
WILMINGTON BUILDINGS TEST.**Details(s) on which inspection and testing were carried out:  
**30/03/16.****C. DETAILS OF THE INSTALLATION**Occupier: **FIRST FLOOR.**Address: **14 SCARLET ROAD, EXTON, WILMINGTON,  
NERSEYSIDE.**Estimated age of the electrical installation: **30 years**Date of previous inspection: **07/03/16**Records of installation available: **✓**Evidence of alterations or additions: **If yes, estimated 10 years age**

Electrical Installation Certificate No or previous Periodic Inspection or Condition Report No:

Records held by: **Client.****D. EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE INSPECTION AND TESTING**

Extent of the electrical installation covered by this report:

**LODGE TESTS.**

Agreed limitations including the reasons, if any, on the inspection and testing:

**NO BACKBOARDS OR GROUND CIRCUITS NOT INSPECTED**Agreed with: **Client.**

Operational limitations including the reasons (see page No. 1)

**none.****E. SUMMARY OF THE CONDITION OF THE INSTALLATION**General condition of the installation (in terms of electrical safety):  
**ok.**

Summary of the condition of the installation continued on additional pages? No Yes Specify page No(s):

**An 'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that further investigation without delay (FD) is required****Overall assessment of the installation:** **SATISFACTORY** **UNSATISFACTORY****Delete as appropriate**

DPM4/ 21088000826

## Contractor's Reference Number

CRN/

**DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT (FOR A SINGLE DWELLING)**

Issued in accordance with British Standard 7671 - Requirements for Electrical Installations.

**A. DETAILS OF THE CLIENT**

Client:

Meadow Apartments Ltd.

Address:

20 Boys Head, St Albans  
Herts SG1 1DE.**B. PURPOSE OF THE REPORT**

Purpose for which this report is required:

Check of consumer unit removal  
Action noted on consumer test.

Postcode:

Date(s) on which inspection and testing were carried out:

30/03/16.

**C. DETAILS OF THE INSTALLATION**

Occupier:

FAT3.

Address:

16 Scary Way, St Albans  
Herts SG1 1DE.

Estimated age of the electrical installation:

30 years

Date of previous inspection:

of

Records of installation available:

✓

Evidence of alterations or additions:

If yes, estimated age

10 years

age

Electrical Installation Certificate No or previous Periodic Inspection or Condition Report No:

✓ Client,

Records held by:

✓

**D. EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE INSPECTION AND TESTING**

Extent of the electrical installation covered by this report:

60, 100, 105.

Agreed limitations including the reasons, if any, on the inspection and testing:

No trackbars cut off.  
not installed.

Agreed with:

client.

Operational limitations including the reasons (see page No. 1).

None.

The inspection and testing have been carried out in accordance with BS 7671, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the client and inspector prior to the inspection.

**E. SUMMARY OF THE CONDITION OF THE INSTALLATION**

General condition of the installation (in terms of electrical safety):

OK.

Summary of the condition of the installation continued on additional pages? No Yes Specify page No(s):

An 'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that further investigation without delay (FI) is required

\* The completed report should preferably be reviewed by another skilled person, competent to confirm that the declared overall condition of the electrical installation is consistent with the inspection and test results, and with the observations and recommendations for action (if any) made in the report. (See declaration on page 2)

This report is based on the moral form shown in Annex D, BSI EN 60364-8-10

Please see the 'Notes for Recipients' on the reverse of this page.

Page 1 of

DPM4/ 0108800327

Contractor's Reference Number

CRN /

**DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT****(FOR A SINGLE DWELLING)**

Issued in accordance with British Standard 7671 - Requirements for Electrical Installations.

**A. DETAILS OF THE CLIENT**

Client:

WACMASTER PROFESSIONAL LTD.

Address:

80 BAUS ROAD, OXFORD, OX1AC,  
MULSEYSDALE.

Postcode:

**B. PURPOSE OF THE REPORT**

Purpose for which this report is required:

LAST INSPECTION GONE ON THAN  
10 YEARS

Date(s) on which inspection and testing were carried out:

30/03/16.

**C. DETAILS OF THE INSTALLATION**

Occupier:

FIZZAT 4.  
14 STANLEY ROAD, OXFORD, OX1AC,  
MULSEYSDALE.

Estimated age of the electrical installation:

30 years

Evidence of alterations or additions  
If yes, estimated 10 years  
age

Electrical Installation Certificate No or previous Periodic Inspection or Condition Report No:

07

Date of previous inspection:

Records of installation available:

Records held by:

CERENT.

**D. EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE INSPECTION AND TESTING**

Extent of the electrical installation covered by this report:

40 : Visual -  
100 ; TESTS:  
Agreed limitations including the reasons, if any, on the inspection and testing:  
NO FLOORBOARDS CLOSER TO THE GROUND  
INSPECTED

Agreed with:

CERENT.

Operational limitations including the reasons (see page No. 1)

None.

The inspection and testing have been carried out in accordance with BS 7671, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the client and inspector prior to the inspection.

**E. SUMMARY OF THE CONDITION OF THE INSTALLATION**

General condition of the installation (in terms of electrical safety):

CERENT.

Summary of the condition of the installation continued on additional pages? No Yes Specify page No(s):

**Overall assessment of the installation:**  **SATISFACTORY / UNSATISFACTORY** \* An 'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that further investigation without delay (F1) is required

**Delete as appropriate**

Please see the 'Notes for Recipients' on the reverse of this page.

This report is based on the model forms shown in Appendix 6 of BS 7671. Published by Current IIP © Current IIP London 2011

Page 1 of 

\* The completed report should preferably be reviewed by another skilled person, competent to confirm that the declared overall condition of the electrical installation is consistent with the inspection and test results, and with the observations and recommendations for action (if any) made in the report. (See declaration on page 2)

DPM4/0108800228

Contractor's Reference Number

CRN/

## A. DETAILS OF THE CLIENT

Client: Wenaston Projects LtdAddress: 80 Bass Road, Ayston, WMA,  
M62 6PS 10E.

## B. PURPOSE OF THE REPORT

Purpose for which this report is required:

1ST INSPECTION GREAT RHTHAN.  
10 YEARS AGO.

Date(s) on which inspection and testing were carried out:

20/03/16

## C. DETAILS OF THE INSTALLATION

Occupier: FAT 5  
Address: 14 Sandy Road, Great BritainEstimated age of the electrical installation: 10 years  
Date of previous inspection: 07/03/16  
Records held by: C CERTEvidence of alterations or additions  
If yes, estimated age:

Electrical Installation Certificate No or previous Periodic Inspection or Condition Report No:

Overall assessment of the installation: SATISFACTORY

Records held by:

Delete as appropriate

Summary of the condition of the installation continued on additional pages?  No  Yes  Specify page No(s):  
**'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that further investigation without delay (F) is required**

## DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT (FOR A SINGLE DWELLING)

Issued in accordance with British Standard 7671 - Requirements for Electrical Installations.

## D. EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE INSPECTION AND TESTING

Extent of the electrical installation covered by this report:

40'; VISUAL100'; TESTS

Agreed limitations including the reasons, if any, on the inspection and testing:

No fault boards tested, etc with unspected.Agreed with: CERT.

Operational limitations including the reasons (see page No. )

No test carried out  
Due to metal around telephone etc

The inspection and testing have been carried out in accordance with BS 7671, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the client and inspector prior to the inspection.

## E. SUMMARY OF THE CONDITION OF THE INSTALLATION

General condition of the installation (in terms of electrical safety):

OK

DPM4/2108800322

# DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT

(FOR A SINGLE DWELLING)  
Issued in accordance with British Standard 7671 - Requirements for Electrical Installations.

Contractor's Reference Number	CRN/
-------------------------------	------

## A. DETAILS OF THE CLIENT

Client:  
**National Mechanics LTD.**

Address:  
**80 Hayes Road, Oxford, OX2,  
MORSEYS 10E.**

Postcode:

## B. PURPOSE OF THE REPORT

Purpose  
for which  
this  
report is  
required:  
**LAST INSPECTION COVERAGE THRU  
10 YEARS.**

Date(s) on which inspection  
and testing were carried out:

**30/03/16**

## C. DETAILS OF THE INSTALLATION

Occupier:  
**FUAT 6**  
Address:  
**14 SAYE ROAD OXFORD OX2 1,  
MORSEYS 10E.**

Estimated age of the  
electrical installation:  
**30 years**

Postcode:

If yes  
estimated  
age  
**10 years**

Evidence of alterations  
or additions  
**✓**

Electrical Installation Certificate No or previous  
Periodic Inspection or Condition Report No:  
**✓**

Records held by:  
**CLIENT**

Records available:  
**✓**

## D. EXTENT OF THE INSTALLATION AND LIMITATIONS ON THE INSPECTION AND TESTING

Extent of the electrical installation covered by this report:

**40% URGAC  
100% TESTS.**

Agreed limitations including the reasons, if any, on the inspection and testing:

**NO FLOOR BOARDS COULD  
NOT BE SPUNTED**

Agreed with: **CLIENT**  
Operational limitations including the reasons (see page No. 1)  
**None.**

The inspection and testing have been carried out in accordance with BS 7671, as amended. Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the client and inspector prior to the inspection.

## E. SUMMARY OF THE CONDITION OF THE INSTALLATION

General condition of the installation (in terms of electrical safety):  
**OK**

Summary of the condition of the installation continued on additional pages? No Yes Specify page No(s):  
**SATISFACTORY** → An 'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that further investigation without delay (FID) is required  
Overall assessment of the installation:  
**SATISFACTORY** → An 'Unsatisfactory' assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified, or that further investigation without delay (FID) is required  
Delete as appropriate

16 Slatey Rd.

# Environet

## Japanese Knotweed removal

Environet UK Ltd  
Clockbarn, Tannery Lane,  
Send, Woking GU23 7EF

Tel 01932 868700

[sales@environetuk.com](mailto:sales@environetuk.com)  
[www.environetuk.com](http://www.environetuk.com)

### Japanese Knotweed Post Treatment Management Plan

*Incorporating your*

### Insurance Backed Guarantee

*Underwritten by*

### Lloyd's Syndicate 4444/958 (Canopius)

Project Ref: 5716

Site/Property Address: 16 Slatey Road, Oxton, Wirral, CH43 4UF

*Japanese knotweed is the UK's no 1 invasive plant. It is easily spread and difficult to completely eradicate. We specialise in the total eradication of Japanese Knotweed and have a dedicated in-house team working nationally to provide our clients with optimised site specific solutions. We are an established company, trading since 1996 with over 1,000 successfully completed projects.*

#### COPYRIGHT NOTICE

This document has been prepared by Environet UK Ltd for the sole use of the person or organisation referred to as beneficiaries, and their representatives. This document is copyright protected and provides potential client sensitive data. It must not be disclosed to other third parties without the prior written permission of Environet®.

Registered in England & Wales No 3204145

Tallford House, 38 Walliscote Rd, Weston super Mare BS23 1LP




£.7.15

Re: 68 Grosvenor Rd,  
Site visit / survey report fee  
£399 inc VAT paid  
Ref: Dug's visa Card.

Jim Key

22/6/15.

14/16 Slatey Rd  
Rear car park.



15.6.16 1st treatment-Jim key-Wet weather.



Clockbarn, Tannery Lane  
Send, Woking GU23 7EF  
Tel 01932 868700  
[sales@environetuk.com](mailto:sales@environetuk.com)  
[www.environetuk.com](http://www.environetuk.com)

Registered in England & Wales No 3204145  
Tallford House, 38 Walliscote Rd,  
Weston super Mare BS23 1LP

## JAPANESE KNOTWEED MANAGEMENT PLAN

14 SLATEY RD, OXTON, WIRREL, CH43 4UF.

Report Ref: 5716-Resi-JKMP-10.06.15.

Contact Name: Macmaster, Graham

Telephone: 07710512082

Email: [admin@macmasterproperties.co.uk](mailto:admin@macmasterproperties.co.uk)

Prepared by: Zac Lowen BSc (Hons)

Report Date: 22/06/2015

£4,475 +VAT  
£5,370 inc VAT.  
inc. 5 yr Guarantee.



In our professional opinion the Japanese knotweed at this property can be successfully eradicated by Environet, once instructed. All of our eradication projects come with our insurance backed guarantee underwritten by LLOYD'S OF LONDON.

LLOYD'S OF LONDON

Japanese Knotweed is the UK's no 1 most invasive plant. We specialise in the rapid eradication of Japanese Knotweed and have a dedicated in-house team working nationally providing our clients with site specific solutions.

### COPYRIGHT NOTICE

This document has been prepared by Environet UK Ltd for the sole use of the person or organisation referred to above, and their representatives. This document is copyright protected and provides commercially sensitive data. It must not be disclosed to other third parties without the prior written permission of Environet.